


DEFEKTŲ NUSTATYMO TAISYKLĖS

PUSPRIEKABIŲ NUOMOS SUTARTIES BENDRŲJŲ SĄLYGŲ Priedas Nr. 2

Šiame dokumente pateikiami vaizdiniai pavyzdžiai:

i) natūralaus nusidėvėjimo, žymimi žalios spalvos ženklų su nykščio simboliu, nukreiptu į viršų;

ii) apgadinimai, kurie nėra laikomi natūraliu nusidėvėjimu bei priskiriami pažeidimams, žymimi raudonu ženklų su nykščio simboliu, nukreiptu žemyn.



Vehicle exterior
Light soiling, exterior



Vehicle interior
Signs of use, clean and complete




Roof tarpaulin
Damaged roof tarpaulin,
water puddle on the floor



Vehicle exterior
Curtain vandalised by graffiti



Vehicle interior
Unclean, untidy return condition



Sliding roof
Defect sliding roof




Inner bulkhead

Inner bulkhead with signs of use




Corner bumpers

Corner bumpers with signs of use



Corner bumpers

Missing corner bumpers, deformed fitting




Inner bulkhead

Inner bulkhead with damages




Corner bumpers

Damaged corner bumpers



Corner bumpers in roller version

Defective corner bumpers



Bulkhead corner support

Bulkhead corner support with signs of use and lock clamp



Rear door

Damaged rear frame (left side)



Side post / rear frame

Damaged rear frame (right side)




Bulkhead corner support

Bulkhead corner support with signs of use, lock clamp missing




Rear door

Punctures in the rear door panel



Rear door


Damaged inner rear door (right side)



Tarpaulin strap
Straps with signs of use (rear left side)




Tarpaulin
Tarpaulin with signs of use




Tarpaulin
Cut in tarpaulin larger than 3 cm



Tarpaulin strap
Damaged strap (rear right side)



Tarpaulin
Non acceptable standard of repair




Curtain spanners
Damaged curtain spanners




Lead in plate
Correctly executed repair



Landing gear
Landing gear with signs of use




Flange
Damage to rim flange



ABS-socket
Missing cover,
bent couplings



Landing gear
Damaged landing gear




Tyre
Damaged face of tyre






Rear marker lights
Defective rear marker lights




Control unit brakes / air suspension
Control unit with signs of use




Document box and customs cable
Document box and customs cable without damages



Frame cross-piece
Bent frame cross-piece through wrongly positioned vehicle jack



Control unit brakes / air suspension
Missing control button



Document box and customs cable
Missing cover from document box and missing customs cable





Mudguards

Damaged mudguards



Underride guard

Underride guard with signs of use



Lateral marker lights

Demolished marker lights



Mud flaps

Missing mud flaps



Underride guard


Deformed underride guard



Rear light unit

Broken lens






Toolbox
Toolbox with signs of use




Alu-drop-in slats
Bent drop-in slats



Spare wheel holder
Deformed spare wheel holder



Toolbox
Damaged toolbox




Alu-drop-in slats
Torn-up drop-in slats



Ladder
Deformed retainer, ladder without function



Sideguards
Sideguards with signs of use




Sideguards
Bent frame fitting



Pallet box
Pallet box with signs of use



Sideguards
Deformed sideguards




Wheel chock
Deformed wheel chock




Pallet box cover
Deformed pallet box cover







Registration and load safety certificate
Complete documentation



Wheel chock
Missing wheel chock




Drop-in slats
Missing drop-in slats



Fire extinguisher box
Fire extinguisher box not complete



Quantity of additional stanchions
Missing additional stanchions



Stack-room for Joloda accessory
Incomplete accessory